

269000



NAVAL AIR STATION FORT WORTH JRB CARSWELL FIELD TEXAS

ADMINISTRATIVE RECORD COVER SHEET

AR File Number 268



DEPARTMENT OF THE AIR FORCE AIR FORCE BASE CONVERSION AGENCY

File: 17A-57 A.F.

268051

28 Sep 95

MEMORANDUM FOR TNRCC

Attn: Mr. Geoffrey Meyer P. O. Box 13087

Austin, Texas 78711-3087

FROM: AFBCA/OL-H

6550 White Settlement Road Fort Worth, TX 76114-3520 Certified Mail

Return Receipt Requested

SUBJECT: Response to 10 Jul 95 TNRCC letter on "Subsurface Contamination at the Base Service Station (BSS)

Attached are AFBCA comments to your 10 Jul 95 letter with appropriate attachments required to meet the 10 October 1995 deadline.

OLEN R. LONG, GM-13

Installation Management Officer

Attachments:

AFBCA Remarks Copy of TNRCC Ltr, dtd 10 Jul 95 DD Form 1391- Project Summary of BSS

cc:

AFBCA/SW - Mr. Ray Hatch TNRCC - Mr. Ray Newby Response to the 10 Jul 95 TNRCC letter on "Subsurface Contamination at the Base Service Station Building 1518, Carswell Air Force Base (AFB), Fort Worth (Tarrant County), Texas (LPST ID No. 104524 - Priority 1.5)

Paragraph I

The Texas Natural Resource Conservation Commission (TNRCC) has carefully reviewed the Existing LPST Case Questionnaire for the above referenced facility submitted August 30, 1994 and prepared by the U.S. Army Corps of Engineers, Ft. Worth District. The questionnaire indicates that this site is considered as a priority 1.5 due to the threat it may pose to the West Fork of the Trinity River. A letter dated August 11, 1994, from Mr. Frank Grey of Carswell AFBCA to Ms. Liz Scaggs of TNRCC PST, indicated that an interim remediation system would be installed on the subject site in late fiscal year (FY) 1994 and a ground water monitoring program would be implemented with comprehensive site assessment activities in FY 1995. Based upon the information provided to this office at this time and recent communications with Mr. Frank Grey of AFBCA, the proposed corrective action activities have yet to be implemented. Please understand that the TNRCC considers the subject site as a high priority case due to the historical release of petroleum hydrocarbons to the West Fork of the Trinity River.

Response: Project 94-7206, RD/RA Base Service Station, is funded for Fiscal Year (FY) 96. This project is a three (3) year project to perform remedial investigations and a risk assessment in FY96, a remedial design and remedial action in FY97, and continuing through project 94-7011, Base Wide Well Monitoring at Carswell AFB (reference contact number F41624-94-D-8050/0001, with Law Environmental). Sampling occurs quarterly and is reported semi-annually. The first semi-annual report is due the first week of October. Upon receipt and acceptance of this contractural deliverable, a copy will be provided to the TNRCC point of contact(s) (POCs). Reviews by AFCEE technical staff (Attachment 1 and 2) recommend not to perform interim remediation until after further remedial investigation reveals the extent of the contamination and a risk assessment is performed (scheduled and funded for FY96). Remedial design and remedial action will occur (FY97/98).

Paragraph II

The TNRCC is responsible for protecting waters of the state as well as public health and safety from contamination that may result when a release occurs from a storage tank system. Title 30, Texas Administrative Code (TAC), Section 334.71-334.85 requires the owner or operator of a storage tank system to immediately abate any release of a regulated substance and to conduct an investigation for soil and groundwater cleanup. A ground water monitoring program using the guidelines in the enclosed pamphlet titles Groundwater Monitoring and Reporting and interim remediation should be implemented immediately. An interim remediation plan must be submitted to this office no later than 60 days from the date of this letter and the first ground water monitoring report must be submitted no later than 90 days from the date of this letter.

<u>Response:</u> A ground water monitoring program is already in place through project 94-7011, Base Wide Well Monitoring at Carswell AFB (reference contact number F41624-94-D-8050/0001, with LAW Environmental). Sampling occurs quarterly and is reported semi-annually. The first semi-annual report is due the October 16, 1995. Upon receipt and acceptance of this contractural deliverable, a copy will be provided to the TNRCC point of contact(s) (POCs).

Remedial design and remedial action will occur (FY97/98). See Attachment 3 for interim remediation plan. Additional documentation will be provided as it becomes available. The Statement of Work (SOW) for the FY96 phase will be available in late October 1995.

Paragraph III

As the responsible party, you are responsible to pursue whatever actions are necessary to minimize any imminent impacts or threats to human health or safety and to stabilize the conditions caused by this release. Should any emergency abatement actions become necessary as a result of this release incident, you must notify the local TNRCC Regional Office immediately. Also, it should be noted that you are liable for third-party losses which may result from this incident.

<u>Response:</u> The Air Force will comply as required.

Paragraph IV

If assessment activities reveal the presence of any phase-separated hydrocarbons (PSH), then you are required, pursuant to 30 TAC 334.79, to immediately implement a recovery program which effectively removes the PSH from all impacted monitor wells, the tankhold, the piping chase, etc., to the maximum extent practicable and to notify this Office immediately. Daily observations should be made and appropriate action pursued to ensure that all phase-separated product is continuously removed.

<u>Response:</u> The Air Force will comply with this requirement.

Paragraph V

Pursuant to 30 TAC Section 334.82 (b), if you determine that contamination from the release has migrated off-site, then you are required to notify the affected landowner(s). Please note that landowners may include state and local owners of right-of-way properties. Please provide documentation that the affected landowner(s) has/have been notified.

<u>Response:</u> Documentation will be provided as required.

Paragraph VI 268004

Submit any additional reports or work plans concerning this case to my attention. Copies of all correspondence with this office must be provided to our Region 4 Field Office in Duncanville to the attention of Mr. Tim Sewell. You are also required to notify Mr. Sewell at 214/298-6171 at lease forty-eight (48) hours in advance of conducting any significant on-site investigation including the performance of groundwater monitoring activities. The LPST ID Number 104524 should be included on all correspondence.


<u>Response:</u> The Air Force will comply with this requirement.

Paragraph VII

Should you have any questions, please contact me at 512/239-2200. Your cooperation in this matter is appreciated.

Response: Cooperation will be provided.

John Hall, Chairman
Pam Reed, Commissioner
R. B. "Ralph" Marquez, Commissioner
Dan Pearson, Executive Director



TEXAS NATURAL RESOURCE CONSERVATION COMMISSION

Protecting Texas by Reducing and Preventing Pollution

July 10, 1995

CERTIFIED MAIL

Mr. Ohlen Long, P.E. Site Manger, AFBCA Carswell Air Force Base 6550 White Settlement Road Ft. Worth, Texas 76114-3520

Re: Subsurface Contamination at the Base Service Station, Building 1518, Carswell Air Force Base (AFB), Ft. Worth (Tarrant County), Texas (LPST ID No. 104524 - Priority 1.5)

Dear Mr. Long:

The Texas Natural Resource Conservation Commission (TNRCC) has carefully reviewed the Existing LPST Case Questionnaire for the above referenced facility submitted August 30, 1994 and prepared by the U.S. Army Corps of Engineers, Ft. Worth District. questionnaire indicates that this site is considered as a priority 1.5 due to the threat it may pose to the West Fork of the Trinity River. A letter dated August 11, 1994, from Mr. Frank Grey of Carswell AFBCA to Ms. Liz Scaggs of TNRCC PST, indicated that an interim remediation system would be installed on the subject site in late fiscal year (FY) 1994 and a ground water monitoring program would be implemented with comprehensive site assessment activities in FY 1995. Based upon the information provided to this Office at this time and recent communications with Mr. Frank Grey of AFBCA, the proposed corrective action activities have yet to implemented. Please understand that the TNRCC considers the subject site as a high priority case due to the historical release of petroleum hydrocarbons to the West Fork of the Trinity River.

The TNRCC is responsible for protecting waters of the state as well as public health and safety from contamination that may result when a release occurs from a storage tank system. Title 30, Texas Administrative Code (TAC), Section 334.71-334.85 requires the owner

Mr. Ohlen Long, P.E. Page 2

or operator of a storage tank system to immediately abate any release of a regulated substance and to conduct an investigation for soil and groundwater cleanup. A ground water monitoring program using the guidelines in the enclosed pamphlet titles Groundwater Monitoring and Reporting and interim remediation should be implemented immediately. An interim remediation plan must be submitted to this Office no later than 60 days from the date of this letter and the first ground water monitoring report must be submitted no later than 90 days from the date of this letter.

As the responsible party, you are responsible to pursue whatever actions are necessary to minimize any imminent impacts or threats to human health and safety and to stabilize the conditions caused by this release. Should any emergency abatement actions become necessary as a result of this release incident, you must notify the local TNRCC Regional Office immediately. Also, it should be noted that you are liable for any third-party losses which may result from this release incident.

If assessment activities reveal the presence of any phase-separated hydrocarbons (PSH), then you are required, pursuant to 30 TAC §334.79, to immediately implement a recovery program which effectively removes the PSH from all impacted monitor wells, the tankhold, the piping chase, etc., to the maximum extent practicable and to notify this Office immediately. Daily observations should be made and appropriate action pursued to ensure that all phase-separated product is continuously removed.

Pursuant to 30 TAC Section 334.82 (b), if you determine that contamination from the release has migrated off-site, then you are required to notify the affected landowner(s). Please note that landowners may include state and local owners of right-of-way properties. Please provide documentation that the affected landowner(s) has/have been notified.

Submit any additional reports or work plans concerning this case to my attention. Copies of all correspondence with this Office must be provided to our Region 4 Field Office in Duncanville to the attention of Mr. Tim Sewell. You are also required to notify Mr. Sewell at 214/298-6171 at least forty-eight (48) hours in advance of conducting any significant on-site investigation including the performance of groundwater monitoring activities. The LPST ID Number 104524 should be included on all correspondence.

Mr. Ohlen Long, P.E. Page 3

Should you have any questions, please contact me at 512/239-2200. Your cooperation in this matter is appreciated.

Sincerely,

Bay Newby

Coordinator, Remediation Unit I

Responsible Party Remediation Section

ERN/ern 104525.cad

Enclosures

cc: Leigh Ing, TNRCC Office of Waste Management
Geof Meyer, TNRCC Industrial and Hazardous Waste Division

Tim Sewell, Region 4 Field Office, 214/298-6171,

(1019 N. Duncanville, Rd., Duncanville, Texas 75116-2201)

1. COMPONENT AFBCA	FY 1995 MILITARY CONSTRUCTION PROJECT DATA				Be	DATE wised 0 Aug 95		
3. INSTALLATION AND LOCATION			4. PROJECT TITLE					
AFBCA/OL-H								
Carswell AFB, TX 76127			RD/RA Base Service Station (ST-16)					
5. PROGRAM ELEMENT		6. CATEGORY CODE	7. F	. PROJECT NUMBER		8. PROJECT COST (\$000)		
BCA]		1					
Budget Program 700)	N/A	DI	OPF 94-720	6	\$3505.0		
		9. CC	OST EST	MATES				
		ITEM		U/M	TITHAUD	Y UNIT COS	ग	COST (\$000)
Phase I								

ITEM	U/M	QUANTITY	UNIT COST	COST (\$000)
Phase I				
Remedial Investigation (New Wells)				100.0
Remedial Investigation			,	139.0
Phase II			į,	
Risk Assessment				236.0
Phase III				
Remedial Design				80.0
Phase IV				
Remedial Action Part 1			,	1325.0
Remedial Action Part 2				1405.0
Phase V				
Long Term Monitoring				220.0
TOTAL PROJECT COST				3505.0

10. DESCRIPTION OF PROPOSED CONSTRUCTION

Project includes all labor, material, equipment, transportation, and support for the remedial desig, risk assessment, remedial action and site inspection of site ST-16, Base Service Station. Work includes extraction wells, biodegradation, groundwater remediation, risk assessment and a decision document/technical report.

<u>PROJECT</u>: Perform interim remediation on an off-base river embankment through the use of three groundwater extraction wells and associated treatment equipment. Additionally, a risk assessment will be performed on the site. If action is determined necessary the remedial design and action will accomplish remediation through the use of biodegredation technology. The remedial design contrator will prepare the decision document and provide Title II inspection service. Project will also include a remedial investigation of the old military gas station (Bldg 1256-1263), which may be contributing to the BSS plume.

REQUIREMENT: (CERFA), Comprehensive Environmental Response Compensation Liability Act (CERCLA), Clean Water Act, Texas Risk Reduction Rules.

CURRENT SITUATION: In May 1992, the base reported a petroleum release into the west fork of the Trinity River. The release point is from the river bed which is located approximately 100 yeards from the base boundary on this site. In October 1992 the first step of the Notice of Violation (NOV) process was started by the Texas Water Commission. A full Remedial Investigation/Feasability Study (RI/FS) which includes the off-base river embankment is being conducted to determine if the source of the river release is this site. The RI/FS will be completed in April 1994. Base Service Station UST's were removed in Spring 1993.

2. DATE 1. COMPONENT FY 1995 MILITARY CONSTRUCTION PROJECT DATA Revised 10 Aug 95 **AFBCA** 3. INSTALLATION AND LOCATION 268009

AFBCA/OL-H Carswell AFB, TX 76127

4. PROGRAM ELEMENT

5. PROJECT NUMBER

BCA Budget Program 700

DDPF 94-7206

IMPACT IF NOT PROVIDED: The Texas Water Commission will issue an additional enforcement action possibly resulting in fines and penalties. Also, the Air Force will not be able to sell or transfer this property until it can meet the requirements of CERCLA section 120h and CERFA. Notice of Violation (NOV) is on the horizon for this one!

muhael J. Kotur

ADDITIONAL

Project Priority:

IA

Contracting Agent:

AFCEE

I have reviewed this requirement and certify that it meets the eligibility criteria for BCA funds

P 555 228 287

RECEIPT FOR CENTIFIED MAIL
NO INSURANCE COVERAGE PROVIDED
NOT FOR INTERNATIONAL MAIL

(See Reverse) U.S.G.P.O. 1989-234-555 Postage Certified Fee CC Special Delivery Fee Restricted Delivery Fee Return Receipt Stragger 10 whom and bate bally PS Form 3800, June 1985 Retyron Eceipus Daile and Address

		A TO CO	
þ	555	228	284

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED

NOT FOR INTERNATIONAL MAIL

(See Reverse)	
Sento Gleoff Meyer Street and No. Postage W. Code 2087	
Street and his Park Circl	e
P.O. State and ZIP Code 3087	
The state of the s	875
Certified Fee	((0
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Grand	(0
Date, and Address of Delivers	
Return Repends of Delivery TOTAL Delivery Postmar or late	,या
Postmar or late 5	
S	

11

P 555 228 286

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Reverse)

	(366 (1676)30)		
n U.S.G.P.O. 1989-234-555	Sept 6 Ment of Ment of Street and Alberta Spark 35	Circle	
9	thustin, h	8123	
חְיֵּ	Postage /	78	
	Certified Fee	(0)	
	Special Delivery Fee		
	Restricted Delivery Fee		
v	Return Receipt showing to whom and Date Delivered	19	
e 198	Return December 10 whom. Date. A corress of Lightery		_
Jun	TOTASTOSISTE and Fees A	5 2 7	_
PS Form 3800, June 1985	Postmandor Day 90		
Form	TIST'S		
PS			

FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE

FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE